

Posner Hall (POS)

Floor 3



All carpet tiles wet. Areas closest to 392A had 1-3 inches of water on floor. Carpet and drywall along baseboards for most of area.

Source of fire
sprinkler line
failure in 392